



CUT


USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS



R3 X2




R1 X2




R2 X2


1



2



3



P1 X2