

CUT



USE A SAW TO REMOVE SUPPORTS FROM 3D PRINTED PARTS

TUBE: D= 0.3 MM, L= 40 MM


REMOVE PROTECTIVE COVER




R1




R2



R3




R4




R5


R6



1



2



3

