



REMOVE PROTECTIVE COVER



USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS



PAINT INSTRUCTION

COLORS	SHADE / ADDRESS	SHADE / MR.COLOR
WHITE	H316	C316
RED	H3	C3
LIGHT GULL GRAY	H11	C11
SEMI GLOSS BLACK		C92

COLORS	SHADE / ADDRESS	SHADE / MR.COLOR
YELLOW	H329	C329
RED BROWN	H131	C131
GREEN	H312	C312