



CUT



R1



R3




R4




R2

USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

1



2



3

