




### CUT



R1



R3



R4




R2

USE A SAW TO REMOVE SUPPORTS  
FROM 3D PRINTED PARTS


### 1

#### DETAILS FROM KIT

CUT



TF




BF


### 2




R2



R1




R3



R4

### 3



DETAIL FROM KIT - BF