




DETAILS AFTER REMOVAL FROM SUPPORTS

USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS



X4 1

