





USE A SAW TO REMOVE SUPPORTS  
FROM 3D PRINTED PARTS


### DETAILS AFTER REMOVAL FROM SUPPORTS




R1



R2



R3 X2



R4 X2

1

